

STEPPING MOTORS TYPE 86BHH156-420G-6GU5K

SPECIFICATIONS				WIRING DIAGRAM
STEP ANGLE	1.8°±5%	VOLTAGE	6.3 V	
NO. of PHASE	4	CURRENT/PHASE	4.2 A	
Inultion Resistant	100Mohm(500VDC)	INDUCTANCE/PHASE	12±20%mh	
Ambient Temperature	-20~40 °C	RESISTANCE/PHASE	1.5±10% Ω	
Operate_Temperature	110 °C Max	HOLDING_TORQUE	100 kg.cm	
WEIGHT	xxx Max			
Ratio	5:1			
The Box allowable load	40N.m Max			

FIGURE UNIT:mm

