

STEPPING MOTORS TYPE 86BHH80-420E-5GU5K

SPECIFICATIONS				WIRING DIAGRAM	
STEP ANGLE	1.8°±5%	VOLTAGE	3.36V	红 A	
NO. of PHASE	4	CURRENT/PHASE	4.2A	黄 B	
Inultion Resistant	100Mohm(500VDC)	INDUCTANCE/PHASE	4.5±20% <i>m</i> H	蓝 C	
Ambient Temperature	-20~40 °C	RESISTANCE/PHASE	0.8±10%Ω	黑 D	
Operate_Temperature	110 °C Max	HOLDING_TORQUE	42Kg _f .cm		
WEIGHT	1.33kg Max	HOLDING_TORQUE			
Ratio	5:1				
The Box allowable load	20N.m max				

FIGURE UNIT:mm

